ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M07687 Client: Alaskan Copper Works

Date Received: 09/22/11 Project: Metro Self Monitor, M07687, F&BI 109321

Date Extracted: 09/27/11 Lab ID: 109321-01 x10
Date Analyzed: 09/27/11 Data File: 109321-01 x10.052

Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 97 60 125

<10

Concentration
Analyte: ug/L (ppb)

 Chromium
 307

 Nickel
 216

 Copper
 187

Zinc

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works

Date Received: Not Applicable Project: Metro Self Monitor, M07687, F&BI 109321
Date Extracted: 09/27/11 Lab ID: I1-677 mb

Date Analyzed: 09/27/11 Data File: I1-677 mb.034
Matrix: Water Instrument: ICPMS1
Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 60 60 125

Germanium 96 60 125

Concentration

Concentration
Analyte: ug/L (ppb)

Chromium <1
Nickel <1

ENVIRONMENTAL CHEMISTS

Date of Report: 09/30/11 Date Received: 09/22/11

Project: Metro Self Monitor, M07687, F&BI 109321

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 109355-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	5.07	91 b	94 b	67-132	3 b
Nickel	ug/L (ppb)	20	7.93	89 b	87 b	73-119	2 b
Copper	ug/L (ppb)	20	582	112 b	0 b	50-144	200 b
Zinc	ug/L (ppb)	50	1,780	120 b	0 b	46-148	200 b

Laboratory Code: Laboratory Control Sample

			Percent						
	Reporting	Spike	Recovery	Acceptance					
Analyte	Units	Level	LCS	Criteria					
Chromium	ug/L (ppb)	20	98	66-135					
Nickel	ug/L (ppb)	20	102	67-134					
Copper	ug/L (ppb)	20	102	66-134					
Zinc	ug/L (ppb)	50	99	57-135					

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

Send Report To Zenza	- 1	mpson		SAMPLERS	(signolute)] _	P	WEO W	ARCUN	of D TIME
Company ALASKA		(1)0	2K5	PROJECT NA							PC			Step RUS	dard M	(2 Weeks	3)
Address 628	Metro SECF monitor mo7687							R	Rush charges authorized by:								
City, State, ZIP_SEA; Phone #206-571-603	RE L	A 9	8734	REMARKS		r:	٠		•					Disp Retu	05e 2		
								_		ANA	LY8	es rieq	UEST	ED			
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	Jaco MEZA					Notes
M07687	01	9/22/4	1:002~	1/20				\exists	1		1	1					
•		ir i					-	+	+	-	-	+					
									1		1						
						_	_	1	+	-	+	_					
						1	1	+	+	+	+						
									1								

Seattle, WA 98119-2029

Ph. (206) 285-8282

Fox (206) 283-5044

FORMS\COC\COC.DOC

SIGNATURE	PRINT NAME	COMPANY	DATE	TIME
Helinguished by:	(Sepas Itompson	MCW	9/2/11	2:19Pm
Received by:	D1 14)	FYBI	9/22/11	11
Relinquished by:			1/-//	7
Received by:			1 -	1

Samples received at 25 °C

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 30, 2011

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on September 22, 2011 from the Metro Self Monitor, M07687, F&BI 109321 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0930R.DOC